



Attorney Docket No. 1594.1309

Colf

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Jin Baek KIM et al.

Application No.: 10/748,229

ATTENTION

Confirmation No.: 7130

CERTIFICATE OF CORRECTION

Filed: December 31, 2003

BRANCH

U.S. Patent No.: 7,066,712

Issued: June 27, 2006

For: TURBOFAN AND AIR CONDITIONER HAVING THE TURBOFAN

**REQUEST FOR CERTIFICATE OF CORRECTION**

Commissioner for Patents  
PO Box 1450  
Alexandria, VA 22313-1450

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 USC § 254 and 37 CFR § 1.322, to correct the error(s) shown on the attached Form PTO-1050. A check in the amount of \$100 to cover the cost of the Certificate is attached.

One or more of the errors shown on the attached Form PTO-1050 is or are within the responsibility of the applicant; each thereof is of a clerical or typographical nature or of minor character and occurred in good faith, and the correction thereof is consistent with the prosecution record.

Respectfully submitted,

STAAS & HALSEY LLP

*Certificate*  
DEC 08 2006  
*of Correction*

Date: Dec. 5, 2006 By: Gene M. Garner, II

Gene M. Garner, II

Registration No. 34,172

1201 New York Ave, N.W., 7th Floor  
Washington, D.C. 20005  
Telephone: (202) 434-1500  
Facsimile: (202) 434-1501

SEARCHED SERIALIZED INDEXED FILED

DEC 11 2006

## UNITED STATES PATENT AND TRADEMARK OFFICE

## CERTIFICATE OF CORRECTION

PATENT NO : 7,066,712

DATED : June 27, 2006

INVENTOR(S) : Jin Baek KIM et al.

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 7, Line 31, after "coupled" insert --to--.

Column 7, Line 38-39, after "direction and" delete "of an axial direction and".

MAILING ADDRESS OF SENDER:  
STAAS & HALSEY LLP  
1201 New York Avenue, N.W.  
7th Floor  
Washington, DC 20005

PATENT NO. 7,066,712No. of add'l copies  
@ 304 per page

⇒

DEC 11 2006